## Work Order ID 53659

November 11, 2009 3:26:39 PM

Н



Page 1

Item ID:

D2221-7

OC:

Accept

Setup Start

Stop

Start

Stop



Revision ID: Item Name:

Rib

**Required Date: 18/11/2009** 

11/11/2009

**Start Oty:** 4.00

**Reg'd Oty:** 4.00



Cust Item ID:

Customer:

Draw

Reference:

Start Date:

Approvals:

Process Plan:

Date: 09/1/2 Tooling:

Date: SPC(Y/N):

Date:

Qty

Run



Sequence ID/

Operation Description Set Up/ Run Hours

Number Rev.

Date:

Draw Plan Code

Accept Qty

Reject Reject Number

Insp. Stamp

Work Center ID Draw Nbr

**Revision Nbr** 

D2221

Rev H

100

Large Fab

Large Fab

Memo

0.00

0.00

Large Fab

1- Cut as per dwg D2221 \( \text{D2- Deburr and remove identification markings on tube} \)



09-12-01

110

Quality Control

OC5- Inspect part completeness to step on W/O

2) & orliz/02

120

Packaging Packaging

Identify as per dwg & Stock Location: WA

Memo

Memo

0.00 SAD 0.00 09-12-02

## Work Order ID 53659

November 11, 2009 3:26:39 PM



Page 2

Item ID:

D2221-7

**Revision ID:** Н

Item Name: Rib

**Start Date:** 

11/11/2009

**Start Oty: 4.00** 

**Reg'd Otv:** 4.00 **Required Date: 18/11/2009** 



Accept

Setup Start

Stop

Start

Stop

Reference:

Approvals:

Process Plan:

QC:

Operation

Description

Date: Date:

**SPC (Y/N):** 

Set Up/

Run Hours

**Tooling:** 

**Cust Item ID:** 

**Customer:** 

Date: Draw

Date:

Draw Plan Accept

Reject

Insp. Stamp

130

Sequence ID/

Work Center ID

**Quality Control** 

Memo

OC21- Final Inspection - Work Order Release

0.00

0.00

Number

Rev.

Code

Qty

Qty

Run

Reject Number

## **Picklist Print**

November 11, 2009 3:26:43 PM

Work Order ID: 53659

Parent Item:

D2221-7RevH

Parent Item Name: Rib

**Comments:** 



Start Date: 11/11/2009

**Required Date:** 18/11/2009

Start Qty: 4.00

Required Qty: 4.00


Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch		Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
M304TS0.750W.065		Purchased	No			100	f	479.3370	19.3861			

Warehouse	Loc	Oty Lo	c Code	•
<b>Location</b>				•
Main Warehouse				·
MAT	473.	6842	_	
113082	473.	6842		<i>19</i> . 3861
Main Warehouse				•
WA	5.652	7947	·	·
112398	5.652	7947		

D2221 BASKET BASE ASSEMBLY (AS350) (MESH SHOWN LOCALLY FOR CLARITY)


SHOP CORY RETURN TO ENGINEFRI':G UNCONTROLL UD CONY SUBJECT TO AMI'NDE AT AT 


`	,			· '					
\	ITEM	QTY	P/N	DESCRIPTION					
7	1	Х	D2221	BASKET BASE ASSEMBLY (AS350)					
	2	1	D2221-1	RIB					
	3	2	D2221-5	RIB					
	4	1	D2221-7	RIB					
	5	2	D2232-3	BASKET HINGE					
	6	2	D2235-1	RIB					
	7	2	D2581	MOUNTING BRACKET					
	8	2	D3442-1	SHIM					
	9	2	D3825-041	RIB ASSY (BASKET END)					
	10	2	D3826-041	RIB/GUSSET ASSY					
	11	1	D3827-041	RIB ASSY (INBOARD)					
	12	2	D3833-1	MESH, BASE END FACE					
	12	1	D2922 1	MECH (DACE)					





н	PARTS C-C (ZN 4). ADD (ZN B2 (SHEET ZN B4-3 041 REF D2221-1	D PARTS LIST LIST (ZN D3-1) C6-3, C2-3 AN ED DETAIL E (; 4); ADDED DW: 5); TOL REVIS ); D3625-041 R PLACES D2235 ON INBOARD N: SATISFY "LE	МВ	08.09.18				
G	TOLERA WAS RE NOW "R TO SHT	AL FOR -1, -3, ANCE FOR 96.( F (ZN B5-2), 19 EF" (ZN B4-2), 2; SHT 2 MESI ERED TO "B"	AJS	08.06.16				
F	ADD SH BASKET	IM UNDER HIN	PH	05.06.07				
E	CHANG	E HINGE	CP	01.04.19				
D	CHANG	E LATCH	BW	96.06.21				
С	SEPARA	ATE BASKET A	KH	95.11.21				
REV.	DESCRIPTION				DATE			
DESIG	7	BW	DART AEROSPACE LTD					
DRAWN 🏂		_ Jb	HAWKESBURY, ONTARIO, CANADA					
CHECKED \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		Nes	DRAWING NO.		REV. H			
MFG. APPR.		- M.	D2221	D2221 SHEET 1 OF 5				
APPROVED (W)		(W)	TITLE SCALE					
DE APPR.			BASKET BASE ASSEMBLY (350) NTS					
DATE	08.0	9.18	COPYRIGHT © 1994 BY DART AEROSPACE LTD THIS COCUMENT IS REMAIR AND CORPORTING AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR NAM PARENS ON COPEDING COMMANDERS TO ANY OTHER PRISON WITHOUT					

NOTES:
1) MATERIAL: N/A
2) FINISH: POWDER COAT GLOSS WHITE (4.3.5.2) PER DART QSI 005 4.3
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: N/A
8) WEIGHT: 42.00 lbs APPROX
9) MASK ALL HOLES PRIOR TO POWDER COATING









NOTES:
1) MATERIAL: AISI 304/316 STAINLESS STEEL SQUARE TUBE, 0.75 X 0.75 X 0.065 WALL REF. DART SPEC. M304TS0.750W0.065
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: N/A
8) WEIGHT: D2221 - 1 = 4.57 lbs; D2221-5 = 0.90 lbs; D2221-7 2.65 = lbs

DART AEROSPACE LTO HAWKESBURY, ONTARIO, CANADA DESIGN DRAWN DRAWING NO. CHECKED REV. H D2221 MFG. APPR SHEET 5 OF TITLE APPROVED BASKET BASE ASSEMBLY (350) NTS
COPYRIGHT © 1994 BY DART AEROSPACE LTD DE APPR.

DATE 08.09.18

		•				
	•				As a second of the second of t	
		:				
				*.		
				· .	American	
		* *		<u>,                                    </u>		ν.
		*				
			<u> </u>	. •		•
			· .			
4.		•			_	
		. '		1	. <b>.</b>	
		i. Objekt			2	
					•	· · · · · · · · · · · · · · · · · · ·
				•		• • •
				300		
#						
					•	•
			•			
and the same of th						
			*			
and the second s		8,				
<b>粉造</b>						
<b>y</b>				•	•	
			•			
			$ x  = \frac{2\pi i}{2\pi} \left( \frac{1}{2\pi} \left( \frac{1}{2\pi$			
		•				
*		• •		V 1		
		•			4	
. <b>'y</b>						
	,		2			
		♥				
	•	<b>3.</b>				
<u>'</u>						
			,			
<u>.</u>		•	e .		•	
. •				,		
				•	<del></del> .	
<b>1</b>			•			
	P.					
	·		, .			